



<b>COMPANY</b> EcoFasten Solar		
<b>PART NUMBER</b> CorruSlide		<b>DATE</b> 7-25-2014
<b>DESCRIPTION</b> Uplift on 28Ga. Steel with 1/4"-14 X 7/8" Blazer Flange VRT Screws		
<b>PRODUCT MATERIAL</b> Assembly		<b>SUBSTRATE</b>
<b>TEST TYPE</b> <input checked="" type="checkbox"/> UPLIFT <input type="checkbox"/> SHEAR <input type="checkbox"/> LEAK TEST <input type="checkbox"/> CLAMP TO SEAM		
<b>TEST NUMBER</b>	<b>LOAD (lb)</b>	<b>REASON For FAILURE</b>
1	836	Bracket Failure
2	741	Bracket Failure
3	816	Bracket Failure
<b>Average</b>	797	
<b>COMMENTS:</b> Images available upon request.		
<i>Internal test data provided at the request and direction of Brian Stearns.</i>		