


Materials Needed for Assembly (see figure 1, Sec. 1-1)

Item No.	Description of Material/Part	Quantity
1	Lag Bolt 5/16"	By Others
2	L-102-3" Bracket * (other options available)	1
3	5/16" EPDM Bonded 18.8 SS Washer	1
4	GF-1	1

Base Components Needed



Required Tools



EcoFasten Solar

EcoFasten Solar® 877-859-3947 Committed to the Support of Renewable Energy