


Materials Needed for Assembly

Item No.	Description of Material/Part	Quantity
1	GF-2 Flashing	1
2	L-202-3" Bracket * (other options available)	1
3	5/16" EPDM Bonded 18.8 SS Washer	1
4	Lag Bolt 5/16"	By Others

Required Tools



EcoFasten Solar