




Materials Needed for Assembly

Item No.	Description of Material/Part	Quantity
1	GF-1 Flashing	1
2	L-102-3" Bracket * (other options available)	1
3	5/16" EPDM Bonded 304-18.8 SS Washer	1
4	Lag Bolt 5/16"	1

Required Tools

