



TEST RESULTS

COMPANY EcoFasten Solar		
PART NUMBER EF-SS-44R-NDD		DATE 12-12-2013
DESCRIPTION See photos		
PRODUCT MATERIAL EF-SS-44R-NDD (8) 2" OMG XHD Deck Fasteners		SUBSTRATE 5/8" OSB
TEST TYPE <input type="checkbox"/> UPLIFT <input checked="" type="checkbox"/> SHEAR <input type="checkbox"/> LEAK TEST <input type="checkbox"/> CLAMP TO SEAM		
TEST NUMBER	LOAD (lb)	REASON For FAILURE
1	4054	Reached Load Cell Limits
2	4047	Reached Load Cell Limits
3	4064	Reached Load Cell Limits
AVG	4055	Reached Load Cell Limits
COMMENTS: Photos available upon request.		
<i>Internal test data provided at the request and direction of Brian Stearns.</i>		





TEST RESULTS

COMPANY EcoFasten Solar		
PART NUMBER EF-SS-44R-NDD		DATE 12-12-2013
DESCRIPTION See photos		
PRODUCT MATERIAL EF-SS-44R-NDD (8) 2" OMG XHD Deck Screws		SUBSTRATE 5/8" OSB
TEST TYPE <input checked="" type="checkbox"/> UPLIFT <input type="checkbox"/> SHEAR <input type="checkbox"/> LEAK TEST <input type="checkbox"/> CLAMP TO SEAM		
TEST NUMBER	LOAD (lb)	REASON For FAILURE
1	2883	Screw pull out
2	2770	Screw pull out
3	2727	Screw pull out
AVG	2793	Screw pull out
COMMENTS: Photos available upon request.		
<i>Internal test data provided at the request and direction of Brian Stearns.</i>		

